

Paper Partition System / 2016 Central Italy earthquake



Year: 2017
Location: Japan
Program: Product Design

Status: Completed
Type: Temporary
Structure: Paper Tube Structure

In central Italy, three earthquakes have occurred in a row since August. The damage caused by the earthquake that occurred on the 30th of October was large, with some important evacuation centers being set up in response. We assembled 50 sets at the center with the help of students in Architecture Faculty at Camerino University. This is the first time for us to install the PPS in a shelter outside of Japan.